REPUBLIK ÖSTERREICH

AUSTRO CONTROL GmbH

LUFTFAHRTINFORMATIONSDIENST Schnirchgasse 17 1030 Wien

AUSTRIA



AUSTRO CONTROL GmbH

AERONAUTICAL INFORMATION SERVICE
Schnirchgasse 17
1030 Wien
AUSTRIA

Phone: +43 5 1703/3211 Telefax:+43 5 1703/2056 AFTN: LOWWYNYX e-mail: nof@austrocontrol.at

REPUBLIC OF AUSTRIA

AIC A 16/23 7 JUL

This AIC replaces AIC A 18/22.

FALSE LOCALIZER CAPTURE

Occurrences of false localizer captures during autopilot and flight director approaches have been reported at a number of airports in Europe in 2010. In some aircraft selection of auto-approach prior to confirmation of LOC centerline can result in false LOC capture.

Pilots are advised to monitor the correct localizer capture.

REF AIP Austria, LOWL AD 2, LOWW AD 2.